

Changelog

Table of Contents

1	Products affected.....	2
2	Fixed bugs	2
3	Upgrade procedure.....	3

1 Products affected

Commercial reference	Product	FW version
LSS100100	Wiser for KNX	2.8.2
LSS100200	spaceLYnk	2.8.2

Table 1: Products affected

2 Fixed bugs

- *If there are 3 short power outages in a row, the project is erased. [Upgrade of firmware 2.8.2 to higher version is required.]*

3 Upgrade procedure

1. Click *Configurator* -> *System* -> *System* -> *Upgrade firmware*
2. Find firmware for your product
3. Click **OK**

Note:

It is highly recommended to create backup of your actual project before upgrade!

We recommend always using the latest firmware because of optimalization of writing data to microSD cards, running services, cyber security etc.

It is recommended to keep an automatic update of IoT 3rd party API (API), Cloud connector applications enabled in order to run Wiser KNX App and avoid incompatibilities.

Check HW version of your logic controller. There are available HW 1.xx, HW 2.xx and HW 3.xx in parallel on the market. HW version is located in the side label of the controller.